



**Item 95 | 185-100 | Slave cylinder piston installation taper tool (not included with product).
This is needed to rebuild the adjustable slave cylinder and re-insert slave cylinder piston.*

Item	Part Number	Item Description	Qty	Assembled as EXP Friction Disk
Document	199-300	CUSTOMER DOCUMENT - Clutch Cover Manual	1	<input type="checkbox"/>
Not Shown	414-709A	Flat Washer M8 x 24mmOD x 2mm Thick	1	<input type="checkbox"/>
Not Shown	418-301A	HARDWARE - Clutch Cover O-Ring Cord-Viton- 22	1	<input type="checkbox"/>
23	169-915A	CLUTCH COVER - H450	1	<input type="checkbox"/>